



There are more than 30 Tenda websites.Tenda Worldwide → <https://www.tendacn.com/region/default.html>

## AC10 v1.0 AC1200 Smart Dual-Band Gigabit WiFi Router Download

Home (<https://www.tendacn.com/us/default.html>) / AC10 v1.0 / Download (<https://www.tendacn.com/us/download/default.html>)

# AC10 v1.0 Firmware

V15.03.06.46

Download

Hardware Version: **V1.0**

### Upgrade Notes:

1.This firmware is only fit for **AC10V1.0** and its firmware version must be in **V15.03.06.XX** or more.

Note: The hardware version marked at the label of devices as below:

2.Do not power off the device when upgrading.

3.Please unzip the file you downloaded and use the file ended with "bin" or "trx" to upgrade your device.

4.Please reset it to factory settings after upgraded it.

### Release Notes:

1.Fixed the problem that DHCP cannot obtain IP under heavy traffic on WAN port.

Please contact us if you have questions [support.usa@tenda.cn](mailto:support.usa@tenda.cn) (<mailto:support.usa@tenda.cn>)

Consumer Products

Whole-Home Wi-Fi

Routers

Modems/ Gateways

Network Expansion

Adapters

Business Products

Switches

Gateway

Optical Access

Enterprise Wireless

CPE&Basestation

Video Surveillance

IP Camera

Network Video Recorder

Video Security Kit

Service Provider

Privacy Statement

Chat with us





[About Us \(//www.tendacn.com/us/profile/default.html\)](http://www.tendacn.com/us/profile/default.html)

[Contact Us \(//www.tendacn.com/us/profile/contact.html\)](http://www.tendacn.com/us/profile/contact.html)

[News \(//www.tendacn.com/us/news/default.html\)](http://www.tendacn.com/us/news/default.html)

[Videos \(//www.tendacn.com/us/videos/default.html\)](http://www.tendacn.com/us/videos/default.html)



---

All rights reserved © 1999-2025 Shenzhen Tenda Technology Co.,Ltd.  
530 Technology Drive Suite#100 Irvine,CA 92618



United States / English/ us  
(//www.tendacn.com/us/region/default.html)